	•		
Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103
Office District I	Energy, Minerals and Natural Resources		Revised June 10, 2003
1625 N. French Dr., Hobbs, NM 88240 District II	OH CONGERNATION DIVIDION		WELL API NO. 30-015-04551
1301 W. Grand Ave., Artesia, NM 88210 District III	NM 88210 OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505		E-9262	
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		North Benson Queen Unit	
PROPOSALS.)	ROPOSALS.) . Type of Well:		8. Well Number
	Other Injection Well	1000	21
2. Name of Operator United Oil & Minerals Limited Partnerskill 3. Address of Operator 1001 Westbank Dr., Austin, TX 78746 United Oil & Minerals Limited Partnerskill 10. Pool name or Wildcat Queen - Grayburg			
3. Address of Operator	linerals Limited Partnership	MED CIA	5300 10. Pool name or Wildcat
	nk Dr., Austin, TX 78746	AR	Queen - Grayburg
4. Well Location			
Unit Letter N: 660 feet from the South of line and 1980 feet from the West line			
Section 27	Township <u>18S</u> Ra	nge <u>30E</u>	NMPM Eddy County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
	PLUG AND ABANDON	REMEDIAL WOR	
<u> </u>	CHANGE PLANS		ABANDONMENT
	MULTIPLE COMPLETION	CASING TEST AN CEMENT JOB	ND 🗌
OTHER:		OTHER: TEMP	PORARILY ABANDON
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
Mechanical Integrity test was run 9-11-03 with proper notice to OCD for witness. See attached chart recording test. Well records show that the packer is set at 2695' on plastic lined 2-1/16" tubing in 2-7/8" casing – TD is 3439'. This is the depth at which a previous operator set the packer in 1974. Perforations are assumed to be no more than 100' below the packer.			
Temporery Abandoned Status approved until 9-11-06			
Congany name change was filed 9-10-03 ws/NMOCD.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Man Culin fatten TITLE Regulatory Coordinator DATE 9/18/2003			
Type or print name Mary Curliss Patton E-mail address: mpatton@uominc.com Telephone No. (512) 328-8184			
(This space for State use)			
APPPROVED BY ORIGINAL TITLE DATE 9-23-03			
Conditions of approval, if any:			
/	•		

