



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON

Governor
Betty Rivera
Cabinet Secretary

Lori Wrotenbery

Director
Oil Conservation Division

Yates Petroleum Corporation
105 South 4th Street
Artesia, New Mexico 88210



Form C-103 Report of Plugging for your *Pathfinder AFT St. #7 SWO - Sec 21-T10S-27E 30-00562725*
Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- ☒ 1. All pits have been filled and leveled.
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed.
- ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Jim Barton
Name
MLG Supsr
Title

date
9-29-03

Van Barton
Field Rep. II

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised June 10, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-005-62775
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-5246
7. Lease Name or Unit Agreement Name Pathfinder AFT State
8. Well Number 7
9. OGRID Number 025575
10. Pool name or Wildcat SWD - San Andres

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-104) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other ☐ Plug & Abandon ☐

2. Name of Operator
Yates Petroleum Corporation

3. Address of Operator
105 South Fourth Street - Artesia, NM 88210

4. Well Location
Unit Letter F : 2310 feet from the North line and 1650 feet from the West line
Section 21 Township 10S Range 27E NMPM Chaves County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3835' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

7-9-2003 - Moved in and rigged up pulling unit and plugging equipment. Nippled down wellhead and nipped up BOP. Rigged up floor and tubing equipment. Released packer. Shut well in for night.

7-10-2003 - POOH with tubing and packer. RIH open ended to 2626'. Spotted 50 sacks Class C Neat cement. POOH with 60 joints. Shut well in. WOC.

7-11-2003 - RIH with tubing and tagged plug at 2230'. Circulated hole with plugging mud. Pulled up hole to 628'. Spotted 25 sacks Class C Neat cement. POOH with tubing. WOC 4 hours. RIH with tubing and tagged plug at 512'. Pulled up hole to 67'. Circulated 15 sacks Class C Neat cement from 67' to surface. POOH with tubing. Rigged down tubing equipment and floor. Nippled down BOP. Rigged down pulling unit and plugging equipment. Cleaned location. Installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT. Plugging completed July 10, 2003. *4603 7-18-03*

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Donna Clack TITLE REGULATORY TECHNICIAN DATE 7-28-03

Type or print name DONNA CLACK E-mail address: _____ Telephone No. 505-748-4227
(This space for State use)

APPROVED BY [Signature] TITLE Field Rep ID DATE _____
Conditions of approval, if any: _____

APPROVED OCT 15 2003