

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

2/11/28  
3000560528

**OPERATOR**

☒ Initial Report

☐ Final Report

Name of Company	Tipton Oil & Gas Acquisition, Inc	Contact	Jim Frazier or Mike Hughes
Address	1131 East Britton Road, Okc, OK 73131	Telephone No.	405-607-6020 or 405-323-8461
Facility Name	O'Brian Fee 19 no. 001 api-30005-60528-0000	Facility Type	Oil Lease & Battery

Surface Owner	Vantan Springs Ranch	Mineral Owner	Various	Lease No.	30005-60528-0000
---------------	----------------------	---------------	---------	-----------	------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	19	8S	29E					Chaves

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Crude Oil	Volume of Release	Aprox 20 Bar	Volume Recovered	Aprox 20 Bar
Source of Release	Tank	Date and Hour of Occurrence		Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Tank failed. Oil Spilled on surface. Rancher notified Producer and OCD. OCD and Producer inspected. Clean up initiated. Initially spill was thought to come from location not owned or operated by Producer. Upon subsequent inspection, Producer confirmed spill location and initiated clean-up.

Describe Area Affected and Cleanup Action Taken.\*

Approx 200 yards of surface area affected. Site is being remediated. Follow-up report will be submitted upon completion and inspection.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Jim Frazier	Approved by District Supervisor: <b>ACCEPTED FOR RECORD</b>	
Title: President	PROCESSED Approval Date: 2-11-08	Expiration Date:
E-mail Address: jfrazier@orbitpetro.com	Conditions of Approval: <b>REMEDATION</b>	Attached <input checked="" type="checkbox"/>
Date: 2-1-2008	WORK PLAN DUE 2-29-08	
Phone: 405-607-6020		

\* Attach Additional Sheets If Necessary

NSEB 0804240934  
PSEB 0804242396

2RP-126