

Summary Report

30-005-63936

Hal Lee
 Rubicon Oil Gas, LLC
 508 W Wall Ave
 Suite 500
 Midland, TX, 79701

Report Date: January 3, 2008

Work Order: 8010303



Project Name: Rhinestone 29 Fed #1

Sample	Description	Matrix	Date Taken	Time Taken	Date Received
146782	N 1/2 Insitu Pit	soil	2007-12-21	08:00	2008-01-03
146783	S 1/2 Insitu Pit	soil	2007-12-21	08:40	2008-01-03
146784	N 1/2 Final Pit Bottom & Sides	soil	2007-12-27	13:00	2008-01-03
146785	S 1/2 Final Pit Bottom & Sides	soil	2007-12-27	13:50	2008-01-03

Sample: 146782 - N 1/2 Insitu Pit

Param	Flag	Result	Units	RL
Chloride		<50.0	mg/Kg	5.00

Sample: 146783 - S 1/2 Insitu Pit

Param	Flag	Result	Units	RL
Chloride		<50.0	mg/Kg	5.00

Sample: 146784 - N 1/2 Final Pit Bottom & Sides

Param	Flag	Result	Units	RL
Chloride		<50.0	mg/Kg	5.00

Sample: 146785 - S 1/2 Final Pit Bottom & Sides

Param	Flag	Result	Units	RL
Chloride		<50.0	mg/Kg	5.00