

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form
OCT 14 2008
OCD-ARTESIA

Release Notification and Corrective Action

OPERATOR

☒ Initial Report

☒ Final Report

Name of Company	OXY USA	Contact	Kelton Beaird
Address	102 S Main Carlsbad, NM 88220	Telephone No. (O)	505-887-8337 C) 575-390-1903
Facility Name	Right Hand Canyon 35-7	Facility Type	Salt Water Disposal/ Tank Battery
Surface Owner BLM		Mineral Owner BLM	Lease No.

30.015.34529

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
3	35	21S	24E					EDDY

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	12-15bbls	Volume Recovered	10 bbls
Source of Release	Valve on unloading line	Date and Hour of Occurrence		Date and Hour of Discovery	10-8-08 @ 9:30am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jim Amos (BLM) Sherry Bohnam (NMOCD)		
By Whom?	Kelton Beaird HES (Oxy)	Date and Hour	See above		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A truck driver left the valve on the unloading line from the tank battery cracked causing oil to fill up containment bucket and overflowing on the location

Describe Area Affected and Cleanup Action Taken.*

All contamination stayed on location. Knapf was put on the spill. This is a very active location. All visible contamination will be hauled off for disposal and backfilled with clean material.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kelton Beaird	Approved by District Supervisor: 	Remediation Actions to be completed and Final C-141 submitted with confirmation analyses/documentation on or before the Expiration Date.
Title: HES Specialist	Approval Date: 10-22-08	Expiration Date: 12-26-2008
E-mail Address: kelton_beaird@oxy.com	Conditions of Approval: SUBMIT CONFIRMATION SOIL ANALYSES FOR APPROVAL PRIOR TO BACK FILLING	Attached <input type="checkbox"/>
Date: 10-10-08	2RP - 258	

* Attach Additional Sheets If Necessary

Notify OCD 48 hours prior to obtaining samples where analyses are to be presented to OCD