

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

DEC 15 2008 Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form  
**OCD-ARTESIA**

**Release Notification and Corrective Action**

**OPERATOR** ☐ Initial Report ☒ Final Report  
Name of Company Fairway Resources LLC Contact Mike Jones  
Address 538 Silicon Dr, Suite 101, Southlake TX 76092 Telephone No. 817-416-1946  
Facility Name Midnight Matador #2 Facility Type oil Well

Surface Owner US-BLM Mineral Owner US-BLM Lease No. NMLC-050138

30-015-34511  
**LOCATION OF RELEASE**

Unit Letter F	Section 35	Township 17S	Range 27E	Feet from the 1950	North/South Line NORTH	Feet from the 2375	East/West Line WEST	County EDDY
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32° 47' 33.14" Longitude 104° 14' 58.09"

**NATURE OF RELEASE**



Type of Release OIL & PRODUCED WATER	Volume of Release 15 BBLS	Volume Recovered 0 BBLS
Source of Release FLOWLINE	Date and Hour of Occurrence 1/14/08 time unknown	Date and Hour of Discovery 1/15/08 1:30 PM MST
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Gerry Guye	
By Whom? Kenneth Pearce	Date and Hour 1/15/08 2:30 pm MST	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Flowline leak; shut in and repaired.

Describe Area Affected and Cleanup Action Taken.\*  
Native pasture near well pad. Basin Environmental supervised excavation, removal of contaminated soil, and replacement with new top soil. All work is completed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Star Hasse	Approved by District Supervisor: 	
Title: Engineering Tech	Approval Date: 12-22-08	Expiration Date: N/A
E-mail Address: shasse@fairwayresources.com	Conditions of Approval: N/A	Attached <input type="checkbox"/> N/A
Date: 12/4/08 Phone: 817-416-1946 x223		

\* Attach Additional Sheets If Necessary

2RP-120