



PHONE (575) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

30-015-36121

ANALYTICAL RESULTS FOR
SWEATT CONSTRUCTION
ATTN: JESSE RODRIGUEZ
720 TEXACO RD.
HOBBS, NM 88240
FAX TO: (575) 391-9895


Receiving Date: 11/17/08
Reporting Date: 11/18/08
Project Number: NOT GIVEN
Project Name: NOT GIVEN
Project Location: JITTERBUG FED. #1


Sampling Date: 11/14/08
Sample Type: SOIL
Sample Condition: COOL & INTACT
Sample Received By: ML
Analyzed By: AB/HM

LAB NUMBER	SAMPLE ID	GRO (C ₆ -C ₁₀) (mg/kg)	DRO (C ₁₀ -C ₂₈) (mg/kg)	418.1 TOTAL TPH (mg/kg)	CI* (mg/kg)
ANALYSIS DATE		11/17/08	11/17/08	11/17/08	11/18/08
H16339-1	1 S/E FRONT PIT	<10.0	<10.0	<100	448
H16339-2	2 S/E HOESHOE OUTSIDE	<10.0	<10.0	<100	80
H16339-3	3 N/E OUTSIDE HOESHOE	<10.0	<10.0	<100	128
H16339-4	4 N/W OUTSIDE HOESHOE	<10.0	<10.0	<100	96
H16339-5	5 S/W OUTSIDE HOESHOE	<10.0	<10.0	<100	448
H16339-6	6 S/W FRONT PIT	<10.0	<10.0	<100	208
H16339-7	7 INSIDE CENTER WESTSIDE	<10.0	<10.0	<100	464
H16339-8	8 INSIDE CENTER EASTSIDE	<10.0	<10.0	<100	< 16
Quality Control		538	443	280	500
True Value QC		500	500	300	500
% Recovery		108	88.6	93.3	100
Relative Percent Difference		0.5	14.8	0.5	2.0

METHODS: TPH GRO & DRO: EPA SW-846 8015 M; EPA 418.1; CI: Std. Methods 4500-CI-B

*Analyses performed on 1:4 w:v aqueous extracts.


Chemist


Date

H16339 TPH2CL SWEATT

PLEASE NOTE Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.



PHONE (575) 383-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR
SWEATT CONSTRUCTION
ATTN: JESSE RODRIGUEZ
720 TEXACO RD.
HOBBS, NM 88240
FAX TO: (575) 391-9895

Receiving Date: 11/17/08
Reporting Date: 11/21/08
Project Number: NOT GIVEN
Project Name: NOT GIVEN
Project Location: JITTERBUG FED. #1

Sampling Date: 11/14/08
Sample Type: SOIL
Sample Condition: COOL & INTACT
Sample Received By: ML
Analyzed By: ZL

LAB NUMBER	SAMPLE ID	BENZENE (mg/kg)	TOLUENE (mg/kg)	ETHYL BENZENE (mg/kg)	TOTAL XYLENES (mg/kg)
ANALYSIS DATE		11/20/08	11/20/08	11/20/08	11/20/08
H16339-1	1 S/E FRONT PIT	<0.050	<0.050	<0.050	<0.150
H16339-2	2 S/E HOESHOE OUTSIDE	<0.050	<0.050	<0.050	<0.150
H16339-3	3 N/E OUTSIDE HOESHOE	<0.050	<0.050	<0.050	<0.150
H16339-4	4 N/W OUTSIDE HOESHOE	<0.050	<0.050	<0.050	<0.150
H16339-5	5 S/W OUTSIDE HOESHOE	<0.050	<0.050	<0.050	<0.150
H16339-6	6 S/W FRONT PIT	<0.050	<0.050	<0.050	<0.150
H16339-7	7 INSIDE CENTER WESTSIDE	<0.050	<0.050	<0.050	<0.150
H16339-8	8 INSIDE CENTER EASTSIDE	<0.050	<0.050	<0.050	<0.150
Quality Control		0.060	0.051	0.055	0.154
True Value QC		0.050	0.050	0.050	0.150
% Recovery		120	102	110	103
Relative Percent Difference		1.7	10.1	5.2	3.3

METHOD: EPA SW-846 8260B

TEXAS NELAP CERTIFICATION T104704398-08-TX FOR BENZENE, TOLUENE, ETHYL BENZENE,
AND TOTAL XYLENES.

Chemist

Date

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims for damages shall be subject to and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.

**CARDINAL LABORATORIES**

101 East Marland, Hobbs, NM 88240

(675) 393-2328 Fax (675) 393-2476

Page ____ of ____

[illegible]

† Cardinal cannot accept verbal changes. Please fax written changes to 676-993-2478.