

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-00802

Release Notification and Corrective Action

0150402338635

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Devon Energy Production Company, L.P.	Contact Jennifer Van Curen
Address P.O. Box 250	Telephone No. 505-748-3371
Facility Name West Red Lake #1 inj	Facility Type Injection

Surface Owner	Mineral Owner	Lease No. 8910089700 Order #WFX-747
---------------	---------------	--

LOCATION OF RELEASE

Unit Letter M	Section 6	Township 18S	Range 27E	Feet from the 810'	North/South Line FSL	Feet from the 960'	East/West Line FWL	County Eddy County
------------------	--------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	-----------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Water	Volume of Release 450 Bbls	Volume Recovered 30 Bbls
Source of Release 2 1/2" injection line	Date and Hour of Occurrence 12-21-03	Date and Hour of Discovery 12-21-03 7:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Don Mayberry-Superintendent Devon, Mike Bratcher OCD, Clarke Bennett-BLM	
By Whom? Jerry Mathews	Date and Hour 12/23/03	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED

JAN 12 2004

OCD-ARTESIA

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Leak in a 2 1/2" injection line (corrosion). Replaced 800' of 2 1/2" tbg with IPC and external wrap tbg. and we are tying it in 1/8/04. We have installed 19 new valves and checked the other 4. We have checked low pressure kills and found that with 2 pumps running the pressure is higher. We will move the low pressure kill to 1175 PSI when we have 2 pumps running and lower for when only 1 pump is running.

Describe Area Affected and Cleanup Action Taken.* Picked up water. A sample was taken 12/30/03 and Cardinal Laboratories report is enclosed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: *Vivian Rodriguez*

Printed Name: Vivian Rodriguez

Approved by District Supervisor:

Title: Tech

Approval Date:

Expiration Date:

E-mail Address: vivian.rodriguez@dvnm.com

Conditions of Approval:

Attached ☐

Date: 12/30/03

Phone: 505-748-5234

* Attach Additional Sheets If Necessary