

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

MAY 04 2010

NMOCD ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

11 SEB1012549380

Release Notification and Corrective Action

30-015-31283

OPERATOR

X Initial Report

☐ Final Report

Name of Company Lime Rock Resources Operating Company, Inc.	Contact Jerry Smith (Operations Foreman)
Address 303 East Main Street, Artesia, N.M. 88201	Telephone No. 575-748-9724
Facility Name Resler State P.W. Transfer pump	Facility Type Water line

Surface Owner State	Mineral Owner State	Lease No.
---------------------	---------------------	-----------

Resler St #1

LOCATION OF RELEASE

Unit Letter P	Section 25	Township 17s	Range 27e	Feet from the 330'	North/South Line FSL	Feet from the 990'	East/West Line FEL	County EDDY
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude 32.79886 Longitude 104.22687

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 80 bbls	Volume Recovered 1 bbl
Source of Release Water Transfer line	Date and Hour of Occurrence 04/26/2010 7:00am	Date and Hour of Discovery 04/26/2010 7:00am
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD/Sherry Bonham	
By Whom? Michael Barrett	Date and Hour 04/26/2010 2:00pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

The flow path for the release did extend into a drainage area that leads ultimately to Logan's Draw.

Describe Cause of Problem and Remedial Action Taken.\*

The poly flow line used to transfer produced water ruptured. The line was taken out of service and repaired. A vacuum truck was immediately brought to the site, free waters were recovered, and water recovered was disposed at an appropriate disposal facility. An emergency one call was made on 04/27/2010 to the New Mexico One Call. Berms were then constructed upgrade of the drainage area to prevent the run off of any rain that might occur. April 28, excavation of the impacted soil began; the excavated soil was transported to Lea Land LLC. and NMOCD approved facility for disposal.

Describe Area Affected and Cleanup Action Taken.\*

The release occurred near the lease road south of the Resler State #1. The release area was measured to be 50 yds x 40 yds. Produced waters flowed downgrade to a road used to maintain an anode bed, the release followed the maintenance road for 100 yds in a narrow flow path est. to be 2' in width. The release entered into a drainage area and then flowed north, the impacted area located in the drainage area was measured to be 70 yds x 7 yds Depth to Ground Water: >100' (approx. 240'), Wellhead Protection Area: 0, Distance to Surface Water Body: >1000'. Site Ranking: 0.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jerry Smith</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Jerry Smith</i>	Signed By: <i>Mike Brannon</i> Approved by District Supervisor	
Title: <i>Operations Foreman</i>	Approval Date: <i>MAY 27 2010</i>	Expiration Date:
E-mail: <i>j.smith@lime.rockresources.com</i>	Conditions of Approval: .	Attached <input type="checkbox"/>
Date: <i>4-30-10</i> Phone: <i>(505) 918-0556</i>	REMEDATION per OCD Rules and Guidelines. SUBMIT REMEDIATION PROPOSAL BY: <i>Remediation</i> <i>in progress 5/17/10</i>	

Attach Additional Sheets If Necessary

PMLB 1014728256

2RP-414