

**RECEIVED**  
**AUG 12 2010**  
**NMOCD ARTESIA**

Submit One Copy To Appropriate District Office  
 District I  
 1625 N. French Dr , Hobbs, NM 88240  
 District II  
 1301 W Grand Ave , Artesia, NM 88210  
 District III  
 1000 Rio Brazos Rd , Aztec, NM 87410  
 District IV  
 1220 S St Francis Dr , Santa Fe, NM 87505

**OIL CONSERVATION DIVISION**  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

Form C-103  
 March 18, 2009

WELL API NO. <b>30-005-63120</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <b>J. Kyle</b>
8. Well Number <b>1</b>
9. OGRID Number <b>160190</b>
10. Pool name or Wildcat <b>Elkins San Andres</b>
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

**SUNDRY NOTICES AND REPORTS ON WELLS**  
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:  Oil Well  Gas Well  Other

2. Name of Operator  
**MEW Enterprise Inc**

3. Address of Operator  
**P.O. Box 39, Roswell N.M. 88202**

4. Well Location  
 Unit Letter **C** : **660** feet from the **N** line and **190** feet from the **W** line  
 Section **26** Township **25** Range **28E** NMPM County **Chaves**

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO:</b> PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/> OTHER: <input type="checkbox"/>	<b>SUBSEQUENT REPORT OF:</b> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input checked="" type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/> <input checked="" type="checkbox"/> Location is ready for OCD inspection after P&A
--	---

- All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
- Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
- A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

**OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.**

- The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
- Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
- If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
- All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
- All other environmental concerns have been addressed as per OCD rules.
- Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE Russell Whitel TITLE President DATE 8-10-10  
 TYPE OR PRINT NAME Russell Whitel E-MAIL: mewent@gmail.com PHONE: 525-420-3324  
 For State Use Only

APPROVED BY: [Signature] TITLE \_\_\_\_\_ DATE 8/16/2010  
 Conditions of Approval (if any):

**DENIED** P/A marker NOT SET in concrete.