

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nkmc 1106139339

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Lime Rock Resources	255933	Contact	Michael Barrett
Address	P.O. Box 2147 Roswell, NM 88202-2147		Telephone No.	575-623-8424
Facility Name	Staley State #6		Facility Type	Oil Well

Surface Owner	C.O.G.	Mineral Owner	State	Lease No.	30-015-37056
---------------	--------	---------------	-------	-----------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
3	30'	17S	28E	1960'	FSL	990'	FWL	Eddy

Latitude 32.803136432 Longitude 104.220424329

NATURE OF RELEASE

Type of Release	Acid & Fresh Water	Volume of Release	214 bbls	Volume Recovered	30 bbls
Source of Release	Broken Nipple on Acid Truck	Date and Hour of Occurrence	2/18/11 @ 10:00 am	Date and Hour of Discovery	2/18/11 @ 10:00 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Randy Dade		
By Whom?	Jerry Smith	Date and Hour	2/18/11 @ 11:15 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Nipple broke on bottom of the acid truck.
P/U standing fluid.

Describe Area Affected and Cleanup Action Taken.*

Ground is rocky with loose soil.
Spread 2000 #'s soda ash and flushed with 130 bbls fresh water. P/U 40 bbls of flush.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Michael Barrett</i>	OIL CONSERVATION DIVISION	
Printed Name: Michael Barrett	Approved by District Supervisor <i>[Signature]</i>	
Title: Production Supervisor	Approval Date: <u>3/7/11</u>	Expiration Date:
E-mail Address: <u>mbarrett@limerockresources.com</u>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <u>2/22/11</u>	Phone: <u>575-623-8424</u>	

* Attach Additional Sheets If Necessary

Jerry Smith: 505-918-0556

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

4/7/11

2RP-624