

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

APR 13 2011

Form C-141
Revised October 10, 2003

NMOCD ARTESIA
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

X Initial Report ☐ Final Report

NMLB1110433805

Name of Company Linn Energy <i>269324</i>	Contact Dennis Potter
Address PO Box 69, Loco Hills, NM 88255	Telephone No. 575 677 2327
Facility Name Turner B #95	Facility Type Oil Well

Surface Owner BLM	Mineral Owner BLM	Lease No. NMLC 029395-B API 30-015-26612
-------------------	-------------------	---

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	20	17S	31E					Eddy

Latitude N32.8201 Longitude W103.8975 (taken at loading station)

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 15bbls Water	Volume Recovered 0bbls
Source of Release Nipple Valve	Date and Hour of Occurrence 30Mar11 0500hrs	Date and Hour of Discovery 30Mar11 0500hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Terry Gregston-BLM	
By Whom? Dennis Potter	Date and Hour 30Mar11 0700hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

The release is a result of a nipple valve failure at the Russell-Turner Water Station. Produced water was released and ran across location towards Linn's office. The affected area is approximately 150' x 150'. The affected area will be delineated to determine the extent of the contamination. Using the lab analysis, a remediation work plan will be developed and presented to NMOCD and BLM for review feedback.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Dennis J. Potter</i>	OIL CONSERVATION DIVISION	
Printed Name: Dennis Potter	Signed By: <i>Mike Branner</i> Approved by District Supervisor:	
Title: Assistant Production Foreman	Approval Date: <i>4/14/2011</i>	Expiration Date:
E-mail Address: dpotter@linenergy.com	Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: <i>5/14/2011</i>	Attached <input type="checkbox"/>
Date: 13Apr11	Phone: 505 206 7673	

* Attach Additional Sheets If Necessary

2RP-744