

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-36555

Release Notification and Corrective Action

NMLB 1115233698

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Lime Rock Resources 25533	Contact	Michael Barrett
Address	PO Box 2147 Roswell, NM 88202-2147	Telephone No.	575-623-8424
Facility Name	Marathon Water Transfer Line	Facility Type	Produced Water Line

Surface Owner	C.O.G. ?	Mineral Owner	State	Lease No.
---------------	----------	---------------	-------	-----------

Assigned to Mora then 26 St #20

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
SW ¼	26	17 S	28 E	330'	FSL	1815'	FWL	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE



Type of Release	Produced Water	Volume of Release	190 bbls	Volume Recovered	130 bbls
Source of Release	Hole in water line	Date and Hour of Occurrence	5/24/11	Date and Hour of Discovery	5/24/11
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	5/25/11 OCD Emergency Extension 5/26/11 Mike Bratcher		
By Whom?	Michael Barrett	Date and Hour	5/25/11		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Hole in 2" steel water line. Isolated line, clamped hole. P/U standing fluid.

Describe Area Affected and Cleanup Action Taken.*
Hot & dry. Leak is @ road crossing @ CR 209 & US 82. Area is 500 +/- long & averages 3' wide. Preparing work & remediation plan. Will sample 5/31/11.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Michael Barrett	Approved by District Supervisor: 	
Title: Production Supervisor	Approval Date: 6/1/2011	Expiration Date:
E-mail Address: mbarrett@limerockresources.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: 5/27/11	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 7/1/2011	

* Attach Additional Sheets If Necessary

2RP-791