

45F

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
NM Oil Conservation Mission
Artesia, NM 89210

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
McKay Oil Corporation

3. ADDRESS OF OPERATOR
P.O. Box 2014, Roswell, New Mexico 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any state requirements. See also space 17 below.)
At surface
1980' FSL & 1980' FEL

5. PERMIT NO. 15. ELEVATIONS (Show whether of ST, GR, etc.)
4278' GR

6. LEASE DESIGNATION AND SERIAL NO.
NM-36194

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
S. 4 Mile Draw Fed. Com

9. WELL NO.

10. FIELD AND POOL OR WILDCAT
W. Pecos Slope Abo

11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA
Sec. 22, T6S, R22E

12. COUNTY OR PARISH
Chaves

13. STATE
NM

RECEIVED BY
FEB -9 1987
O. C. D.
ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT OFF	BUILD OR ALTER CASING	WATER SHUT OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETION	FRACTURE TREATMENT	ALTERING CASING
SHUT IN OR ABANDON	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
PLUG WELL	CHANGE PLANS	OTHER:	

17. DESCRIBE THE NATURE OF OPERATIONS TO BE PERFORMED, PERTINENT DETAILS, AND GIVE PERTINENT DATES, INCLUDING ESTIMATED DATE OF STARTING AND PROPOSED WORK. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.

Note: Report results of multiple completion on Well Completion or Reservoir Completion Report and Log form.

Operator proposes to construct an access road 14' wide by approximately 900' in length as displayed on the enclosed topographic map.

An archaeological survey was conducted by Archaeological Survey Consultants, January 3, 1987, under report #87-6.

*Jw8
1/27/87
Coliche pit for access road is pad:
NW/4 SE/4
Sec 9, T6S, R22E*



18. I hereby certify that the foregoing is true and correct


SIGNED Serry W. Franklin TITLE Landman DATE 1/22/87

(This space for Federal or State office use)

APPROVED BY S/Phil Kirk TITLE Area Manager DATE FEB 2 1987

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side



RECEIVED

1954