

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office \_\_\_\_\_  
Lease No. LES CRUCES  
062623-3  
Unit \_\_\_\_\_

APPROVED  
SEP 25 1963  
L. L. BUCKLEY  
ACTING DISTRICT ENGINEER

RECEIVED

SEP 26 1963

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

B. C. C.  
ARTESIA, OFFICE

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 9 is located \_\_\_\_\_ ft. from 8 line and \_\_\_\_\_ ft. from W line of sec. \_\_\_\_\_

330 330 33

(1/4 Sec. and Sec. No.) 180wp. 27 Range) (Meridian)

(Field) Artesia (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

100- foot plug ( 20 sacks) at 325-425 feet  
 100- foot plug ( 20 sacks) at 110-210 feet  
 20- foot plug ( 4 sacks) from surface to 20 feet  
 Hole filled with mud between plugs  
 set regulation marker  
 Filled pits cleaned & leveled location

RECEIVED  
SEP 24 1963  
U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company American Employers' Insurance Co.

Address Box 437

Artesia, New Mexico

By \_\_\_\_\_

Title Agent