NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

REPORT ON BEGINNING Drilling operations		REPORT ON RESULT OF TEST OF CASING SHUT-OFF	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL	x	REPORT ON RECOMPLETION OPERATION	REPORT ON (Other)	
		April 25, 1950	Artesia, New Mexico	
Following is a report on the	work done	and the results obtained under the he	ading noted above at the	
Murchison and Clos	or Operator)		State (Case)	
(Con	tractor)	, Well No. 1	in the SE 1/4 of NE 1/4 of Se	c. 16
		rg-Jackson Poo	ı, Eddy	Coun
		ch 27 through April 3,		
	(/	obtained.		
Mudded hole to 3290 pulled same. Mudd	ETAILED A O', set 5 led hole	ccount of work done and sax cement bridge. Cu to 630' set 5 sax cement	results obtained at 7" casing at 1250' and bridge, cut 8-1/4" casing te, set regulation marker	
Mudded hole to 3290 pulled same. Muddat 1861 and recover	ETAILED A O', set 5 led hole	ccount of work done and sax cement bridge. Cu to 630' set 5 sax cement	at 7" casing at 1250' and the bridge, cut 8-1/4" casing	
Mudded hole to 3290 pulled same. Muddet 106' and recover in cement.	O', set 5 led hole ed same	sax cement bridge. Cuto 630' set 5 sax cement. Mudded hole to surface. Ackerman Well S	ervice Owner (Title)	
Mudded hole to 3290 pulled same. Muddet 1060 and recover in cement.	erailed A O', set 5 led hole ed same	sax cement bridge. Cuto 630' set 5 sax cement. Mudded hole to surface. Ackerman Well S (Company)	t 7" casing at 1250' and the bridge, cut 8-1/4" casing te, set regulation marker	d comple
Mudded hole to 3290 pulled same. Muddet 106' and recover in cement. Witnessed by E. D. Ack (Na	erailed A O', set 5 led hole ed same	sax cement bridge. Cuto 630' set 5 sax cement. Mudded hole to surface. Ackerman Well S (Company)	ervice city that the information given above is true and my knowledge. Outside the control of the control of my knowledge. Outside the control of the control of my knowledge.	d compl

(Date)

Address San Antonio, Texas

(Title)