

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate
(Other instructions
on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

458

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
ARCO OIL AND GAS COMPANY

3. ADDRESS OF OPERATOR
BOX 1710, HOBBS, NEW MEXICO 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
900' FSL and 1980 FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3590 GR

RECEIVED

APR 18 '89

C. D.

OFFICE

6. LEASE DESIGNATION AND SERIAL NO.
LC 031844

7. INDIAN, ALLOTTEE OR TRIBE NAME

8. AGREEMENT NAME

9. NAME OR LEASE NAME
FREN OIL COMPANY

10. WELL NO.
7

11. FIELD AND POOL, OR WILDCAT
CEDAR LAKE ABO

12. SEC., T., R., M., OR BLK., AND
SURVEY OR AREA
19-17S-31E

13. COUNTY OR PARISH
LDDY

14. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other) TEMPORARILY ABANDON

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, location, and estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

TD - 7036' PBD - 6875 (CIBP) PERFS - 6928-82
RKB - 12' 6" 600 W.H. 4 1/2" CSG

3-29-89 MIRU SDON.

3-30-89 R/O B/D well. Kill well w/32 BBL PW. NDWH NUBOP. POH w/1 jt P.U. Rental string RIH w/tbg. 109 jt in hole. Well head starting to deflect. POH w/tbg. Rig down for well head repair.

3-31-89 MIRU B/D well. R.U. to run RBP 4 1/2. WH broke off. RUN RBP to 1559 (50 jts). Set & POH. P.U. csg. Spear RIH w/spear set & P.U. csg. Remove slips, stack 4 1/2 release spear. POH. R.O. SDOWD to replace 3 5/8 & 4 1/2 at surface.

4-03-89 Note: 1 bag 20/40 sand on top of RBP. RU PU. PU WS & RIH to catch RBP. Circ. sand off RBP & latch on, rlse & POH w/RBP. RIH w/3 7/8" bit & 4 1/2" csg scraper. RIH to CIBP @ 6875' & circ hole clean. POH w/tbg SDFN.

4-04-89 PU pkr & RIH w/221 jts tbg. Set pkr w/10 pts. RU swab & swab 71 BW. SFL 1400'-3000'. FFL - 3000'. Onlast run sand line parted. SDFN.

4-05-89 RU swab & swabbed 54 BW. Total load water was 97 BW & total recovered was 125 BW. Very little show of oil. RD swabber & POH w/tbg. SDFN. Obtained verbal approval to TA from Shannon Shaw (BLM Carlsbad).

4-06-89 RU Bell WL & set CIBP @ 6825'. RD WL. RIH w/tbg OE to circ. hole w/treated brine water. Test csg to 500# w/chart recorder. Press. csg 30 min. POH LD tbg. RDMO. PU Well TA'd 10:00 a.m. 4-6-89. (Chart attached)

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]*

TITLE Services Supervisor

DATE 4-7-89

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

DATE

APPROVED FOR 12 MONTH PERIOD

APR 14 1989

ENDING 4/14/90

*See Instructions on Reverse Side

SJS
CARLSBAD, NEW MEXICO

