Form 9-331a
(May 1939)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Blake #1

_____ March 20 _____, 1944

Well No. ___1___ is located ___330___ ft. from {N/S} line and ___2310___ ft. from {E/W} line of sec. ___6___

NW¼ NE¼   6   17 S.   29 E.   N.M.P.M.
___(¼ Sec. and Sec. No.)___   ___(Twp.)___ ___(Range)___   ___(Meridian)___

Carper Drlg. Co.   Eddy   New Mexico
___(Field)___   ___(County or Subdivision)___   ___(State or Territory)___

The elevation of the derrick floor above sea level is .... ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Seventeen sacks of mud were pumped through tubing to fill bottom of hole from 2440' to 2390'. Tubing was then knocked off at 1985'. Mud was circulated through tubing. Tubing was then pulled to 1400' and a ten sack cement plug was run. Tubing was then pulled to 400' and a ten sack cement plug was run. Tubing was then pulled out of hole, a 4" marker was set in a five sack plug at the surface.

P&A approved
3-20-44

RECEIVED
MAR 30 1944
ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company ___CARPER DRILLING COMPANY___

Address ___Artesia, New Mexico___

By _____

Title ___Partner___