

Form 9-331  
(May 1963)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other Instructions on reverse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 028731 a

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Moran Oil Producing & Drilling Corp. ✓		8. FARM OR LEASE NAME Dodd	
3. ADDRESS OF OPERATOR P. O. Box 1919, Hobbs, New Mexico 88240		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980/S & 1880/E Section 22, T17S, R29E, Eddy County, New Mexico		10. FIELD AND POOL, OR WILDCAT Grayburg Penn <i>et alia</i>	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3551 GL	
		12. COUNTY OR PARISH Eddy	13. STATE N.M.

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

On 4-26-71 the above well reached total depth of 10,880'. Drill stem tests and logs indicated the well to be non-productive on 4-27-71. Verbal approval was obtained from the Artesia office of the U.S.G.S. On 4-27-71 the following cement plugs were set with 9# mud between each:

35 sx	10,300 - 10,200
35 sx	8900 - 8800
35 sx	7300 - 7200
35 sx	5500 - 5400
35 sx	3450 - 3550

Additional plugs will be set after 8 5/8 is pulled.

RECEIVED  
MAY - 4 1971U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICORECEIVED  
APR 29 1971  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

*Cal M. G. [Signature]*

TITLE

Agent

DATE 4-28-71

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD PURPOSES  
MAY - 4 1971  
Date  
DISTRICT ENGINEER

\*See Instructions on Reverse Side

RECEIVED

MAY 5 - 1971

O. C. C.  
ARTESIA, OFFICE