Copy to SF 5-USGS-ARTESIA MMOCC COPY 1-FILE UNITED STATES SUBMIT IN TRIPLICATE®

DEPARTMENT OF THE INTERIOR (Other instructions on reverse side) Form 9-331 (May 1963) Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO. GEOLOGICAL SURVEY LC-029418-A 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.) 1. 7. UNIT AGREEMENT NAME WE'L X GAS WELL SKELLY UNIT OTHER 8. FARM OR LEASE NAME 2. NAME OF OPERATOR GETTY OIL COMPANY SKELLY UNIT 3. ADDRESS OF OPERATOR 9. WELL NO. RECEIVED P. O. BOX 730, HOBBS, NEW MEXICO 88240 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface 120 10. FIELD AND POOL, OR WILDCAT FREN 7-RIVERS JAN 16 1978 760' FSL & 760' FWL 11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA Sec. 14, 175-31E O. C. C. 15. ELEVATIONS (Show whether DF, RT, CA, etc.) SIA, OFFICE 12. COUNTY OR PARISH 13. STATE 14. PERMIT NO. 3880' GR N.M. 18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PULL OR ALTER CASING REPAIRING WELL TEST WATER SHUT-OFF WATER SHUT-OFF MULTIPLE COMPLETE FRACTURE TREATMENT ALTERING CASING FRACTURE TREAT ABANDON* ABANDONMENT* SHOOT OR ACIDIZE SHOOTING OR ACIDIZING REPAIR WELL CHANGE PLANS NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Spudded 11" hole 2:30 P.M. 8-28-77. Drilled to 636' 10-29-77. Set 8-5/8" 24# 8Rd Casing at 636'. Howco cemented w/125 sxs. Howco Lite and 125 Sxs. Class "C" W/2% CaCl₂/Sk.-total of 250 Sxs. Cement Circulated Waiting On Cement - 12 Hours. Tested 8-5/8" Casing to 1000# for 30 Minutes. No Drop in Pressure.

RECEIVED

JAN 12 1978

			N. S. GEOLDEN MEN.
18. I hereby certify that the foregoing is true and correct SIGNED Dale R. Crockett	TITLE _	AREA SUPERINTENDENT	DATE 1-9-78
(This space for Federal of State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE _	ACTING DISTRICT ENGINEER	DATE JAN 1 3 1978
		D	