




R.D.C., INCORPORATED

Petroleum Exploration • Drilling • Production



VERIFICATION OF DEVIATION SURVEYS

WELL NAME AND NUMBER CAVE STATE NO. 1
LOCATION Section 4, Township 17 South, Range 29E - 330' FNL & 330' FWL
OPERATOR DIAMONDBACK PETROLEUM
DRILLING CONTRACTOR RHYMES DRILLING COMPANY, INC.

The undersigned hereby certifies that he is an authorized representative of the drilling contractor who drilled the above described well and has conducted deviation tests and obtained the following results:

DEGREES OF DEVIATION	AT A DEPTH OF
<u>3 degrees</u>	<u>990'</u>
<u>2-1/2 degrees</u>	<u>1041'</u>
<u>2-1/4 degrees</u>	<u>1133</u>
<u>1-3/4 degrees</u>	<u>1285'</u>
<u>1 degree</u>	<u>1852'</u>
<u>1/2 degree</u>	<u>2316'</u>
<u>1/2 degree</u>	<u>2540</u>
<u> </u>	<u> </u>
<u> </u>	<u> </u>
<u> </u>	<u> </u>

DRILLING CONTRACTOR: RHYMES DRILLING CO., INC.

BY: L.L. Liveoak, Operations Manager

SIGNATURE: *L.L. Liveoak*