

UP
37

GEOLOGICAL SURVEY WELL STATUS REPORT

Section	Township	Range
26	18S	25E
Footage Location of Well:		
990	feet from North	line
2310	feet from West	line
Pool		
Penasco Draw (Yeso S.A.)		
COUNTY		STATE
Eddy		N.M.

(To be submitted in quintuplicate on all inactive wells)

NAME AND ADDRESS OF OPERATOR
~~Yates Petroleum Corporation~~ - Artesia, NM 88210
 207 South 4th Street

MARTIN YATES III
 WELL NO. AND LEASE NAME
 1 ~~Federal~~ LDY

LEASE NO.
0630

RECEIVED

JUN 24 1976

O.C.C.
ARTESIA, OFFICE

1. When Was Well Shut-in or Last Produced?

September, 1974

2. Type Well

Oil Well Gas Well Temp. Abd. Well

3. Producing Capability

BOPD 0.2 MCFGPD TSTM

BWPD 0.3 Date Last Tested _____

4. Is Well Considered Capable of Production in Paying Quantities?

Yes No

5. If Capable of Producing in Paying Quantities, Give Reasons For Not Producing Well.

6. If Not Capable of Producing in Paying Quantities, Give Reasons For Not Plugging Well At This Time.

Well is in area of intensive secondary recovery potential, and well is being studied for remedial work

7. What Are Future Plans For Operating Well (Include Estimated Dates)?

Well will be utilized in Secondary Recovery program in 4 or 5 years.

RECEIVED
JUN 18 1976
D. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

I hereby certify that the foregoing is true and correct.
SIGNED *Eddie L. Breekman*

TITLE Engineer

DATE 6-17-76

(This space for Federal or State office use)

APPROVED

 L. BREEKMAN
 ACTING DISTRICT ENGINEER

JUN 22 1976

TITLE _____ DATE _____

UNLESS FURTHER APPROVED, WELL MUST
BE PUT TO BENEFICIAL USE OR PLUGGED BY
APRIL OCT 1 - 1976