

## MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company <b>Jones &amp; Haile</b>		Address <b>Box 1225, Artesia, New Mexico</b>				
Lease <b>Featherstone-State</b>	Well No. <b>1</b>	Unit Letter <b>J</b>	Section <b>32</b>	Township <b>19 S</b>	Range <b>27 E</b>	
Date Work Performed <b>May 13, 1960</b>	Pool <b>McMillian</b>			County <b>Eddy</b>		

THIS IS A REPORT OF: (Check appropriate block)

- Beginning Drilling Operations     
 Casing Test and Cement Job     
 Other (Explain):  
 Plugging     
 Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

We ran 453 feet of 5½ inch 14# casin and cement with 13 sacks of cement. It was calculated to have lapped into the 7 inch surface pipe.

Witnessed by <i>J. Truett Hill</i>	Position <b>Agent</b>	Company <b>Jones &amp; Haile</b>
---------------------------------------	--------------------------	-------------------------------------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

## ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

## RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

## OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by <i>W. A. Gossart</i>	Name <i>J. Truett Hill</i>
Title <i>Agent</i>	Position <b>Agent</b>
Date <i>MAY 20 1960</i>	Company <b>Jones &amp; Haile</b>