

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRODUCTION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION **REC'D** FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS **SEP 20 1961**

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company **John A. Yates** Address **323 Carper Building, Artesia, N.M.**

Lease **Caroline** Well No. **3** Unit Letter **D** Section **28** Township **19S** Range **28E**

Date Work Performed **9-19-61** Pool **Angell Seven Rivers Undes.** County **Eddy**

THIS IS A REPORT OF: (Check appropriate block)

- Beginning Drilling Operations Casing Test and Cement Job Other (Explain): **Perforating & Acidizing**
 Plugging Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Perforated from 1205-1199; 1177-1175; 1160-1157; 1152-1149; & 1144-1142.

Acidized with 13,000 gallons of acid.

Swabbed and got 35 barrels of oil and 20 barrels of water in 24 hours.

Witnessed by _____ Position _____ Company _____

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev. _____ T D _____ P BTD _____ Producing Interval _____ Completion Date _____

Tubing Diameter _____ Tubing Depth _____ Oil String Diameter _____ Oil String Depth _____

Perforated Interval(s) _____

Open Hole Interval _____ Producing Formation(s) _____

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by **ML Armstrong**
Title **OIL AND GAS INSPECTOR**

Name **Walter Pae**
Position **Secretary**

Date **SEP 21 1961**

Company **John A. Yates, 323 Carper Bldg; Artesia**