

(505) 393-0119

STEP RATE TEST RECEIVED

NEW MEXICO

FIELD DATA SHEET

APR 22 1983

Type Test:

☐ Initial☐ Annual☐ Special

Test Date

4/19/83

Lease No. or Serial No.

Company

Clifford Cone Co

ARTESIA, OFFICE

Allottee

Field

Reservoir

Location

Unit

Completion Date

Total Depth

Plug Back TD

Elevation

Form or Lease Name

Culwin Queen

Csg. Size

Wt.

d

Set At

Perforations: From

3092

To 3126

Well No.

Unit #13

Tbg. Size

2 3/8"

Plastic coated

Set At

Perforations: From

To ut A

Sec.

Twp - Bk

Rge -

Type Completion (Describe)

Water Injection Well

Packer Set At

3070

County or Parish

Lea

Eddy

Producing Thru

Reservoir Temp. F

Mean Ground Temp. F

Baro. Press. - P

State

N.M.

CO. REPRESENTATIVE

DATE	ELAP. TIME	Well information			surf.	remarks	
Time of Reading	Hrs.	Rate BPD	Surf. Psig	B.H.P.	psi. cor. friction	(Include liquid production data: Type - API Gravity - Amount)	
9:45	SHUT IN		760			1417 Colum wt.	Bombs @ 3100
10:05	BOMB @ BOTTOM						
10:15	START PUMPING	760	760	2177			
10:30	:15	120	805	2220		STEP #1	
10:30							
10:45	:30	330	880	2300		2	
10:45							
11:00	:45	575	990	2428		2" TURBIN	10:48 - Running out of water-switch to kill truck.
11:00	:45						
11:15	1:	1000	1280	2601	1184		
11:15							
11:30	:15	1585	1520	2816	1399		
11:30							
11:45	30	2160	1720	2989	1572		
11:45	45	2740	1940	3092	1675		
12:00							
12:15	2	3170	2050	3176	1759		
12:15							
12:20	15	3890	2240			ONLY RAN 5 MIN. RUN OUT OF WATER	
						INSTANT SHUT IN P.S.I. 1705	

CLIFFORD CONE CO.
CULWILN QUAREW
UNIT #13
4-19-83



