m 3160-5 ne 1990)

any matter within its jurisdiction

UNITED STATES DEPARTMEN. OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED

Budget Bureau No. 1004-0135 Expires March 31, 1993 5. Lease Designation and Serial No. SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. NM10190 Use "APPLICATION FOR PERMIT—" for such proposals 6. If Indian, Allottee or Tribe Name SUBMIT IN TRIPLICATE 7. If Unit or CA, Agreement Designation 1. Type of Well ⊠ Oil Well ☐ Gas ☐ Other 14-08-001-11572 8. Well Name and No. 2. Name of Operator **DEVON ENERGY CORPORATION (NEVADA)** East Shugart Unit #21 9. API Well No. 3. Address and Telephone No. 20 NORTH BROADWAY, SUITE 1500, OKLAHOMA CITY, OKLAHOMA 73102 (405) 235-3611 30-015-05693 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage. Sec., T., R., M., or Survey Description) 2310' FSL & 1650' FWL Sec. K-35-18S-31E Shugart (Y-SR-Q-G) 11. County or Parish, State Eddy, NM CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Change of Plans Recompletion **New Construction** Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Final Abandonment Notice Altering Casing Conversion to Injection Other Integrity Test Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Ran mechanical integrity test 11-14-94. RU pump truck and load csg w/water.) Pressure tested csg to 500 psi APR 20 1995 for 30 mins. OK. Chart attached. Witnessed by J. D. Whitlock (BLM). Our injection facilities do not have sufficient capacity to handle additional produced water. preparing to expand these facilities and this work is expected to be completed in six months. At that time, the well will be returned to production. Therefore, we request TA status for six months. THAPPROVED FOR 6 EMDING 14. I hereby certify that the foregoing is true and correct CANDACE R. GRAHAM ENGINEERING TECH. Date 4/13/95 6 6 (This space for Federal or State office use) (ORIG. SGD.) JOE G. LARA Petroleum Engineer Approved by Title: Conditions of approval, if any

