

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME East Shugart Unit WF	
2. NAME OF OPERATOR Atlantic Richfield Company ✓		8. FARM OR LEASE NAME East Shugart Unit	
3. ADDRESS OF OPERATOR P. O. Box 1710, Hobbs, New Mexico 88240		9. WELL NO. 12	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface  2310' FNL & 990' FWL (Unit letter E)		10. FIELD AND POOL, OR WILDCAT Shugart Queen	
14. PERMIT NO.		13. STATE N.M.	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3635' CTF		12. COUNTY OR PARISH Eddy	

RECEIVED

SEP 8 1978

D.C.C.  
ARTESIA, OFFICE

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) Temporary Abandoned ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

## 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This well was temporarily abandoned in the following manner:

1. Rigged up, POH w/completion assy.
2. RIH w/CIBP w/junk pusher on 2-3/8" OD tbg.
3. Set BP @ 2650'. POH w/tbg.
4. Circ csg w/110 BFW cont'g 11 gals C-198 corrosion inhibitor.
5. RIH w/1 jt 2-3/8" OD EUE tbg (31'), packed off wellhead. Installed gate valve in top of tbg. Closed csg valves.

Temporarily abandoned 8/7/78. Hold for possible future use in waterflood unit.

RECEIVED  
SEP 5 1978  
U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

## 18. I hereby certify that the foregoing is true and correct

SIGNED J. L. LoraTITLE Sr. Dist. Prod. Supv.DATE 9/1/78

(This space for Federal or State office use)

APPROVED BY J. L. LoraTITLE ACTING DISTRICT ENGINEERDATE SEP 7 - 1978

CONDITIONS OF APPROVAL, IF ANY:

UNLESS FURTHER APPROVED, WELL MUST  
BE PUT TO BENEFICIAL USE OR PLUGGED BY  
APRIL OCTOBER 1, 1979

\*See Instructions on Reverse Side