

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-10191

6. IF INDIAN, ALLOTTEE, OR TRIBE NAME

7. UNIT AGREEMENT NAME

East Shugart Unit

8. FARM OR LEASE NAME

East Shugart Unit

9. WELL NO.

10

10. FIELD AND POOL, OR WILDCAT

Shugart-Yates/Queen

11. SEC., T., R., M., OR BLK. AND

Sec. 35, T18S, R31E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Atlantic Richfield Company

3. ADDRESS OF OPERATOR

P.O. BOX 1978, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

2310' FNL, 2310' FEL (Unit Letter F)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3646' CTF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

Remedial Cement

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

MI unit 10/20/69. CO w/sand pump from 3919-3926 (PBD). Set BP @ 3523'. Ran CGL from 3515-1900', indicated top of cement @ 2214'. Added Queen perforations w/one 1/2" JS ea @ 3381, 3385, 3448, 3457, 3466, 3474, 3480 & 3485 (8 holes, GR-N log). Tested BP to 2500#, OK. Treated above perms w/1000 gal 15% LSTNE HCl acid & ball sealers; frac'd w/35,000 gal slick fresh water containing 22,000# 20/40 sand. Pld BP. Ran 2-3/8" production tubing string w/pump and rods. Returned well to production. Now pumping load water. Work completed 10/28/69.

RECEIVED

OCT 31 1969

D. S. GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO

RECEIVED

NOV 19 1969

OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED

D. D. Dutcher

TITLE

Dist. Drlg. Supervisor

DATE

10-29-69

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

RECORD

DISTRICT ENGINEER

TITLE

DATE

*See Instructions on Reverse Side