


SCOUT REPORT NEW MEXICO

OIL CONSERVATION COMMISSION



Company Rip C. Underwood
 Farm Name Bruce Well No. 1
 Land Classification _____
 Sec. 4 Twp. 19 Range 31 County Eddy
 Feet from Line: N. 2310 S. 330 E. _____ W. _____
 Elevation _____ Method Ret.
 Contractor Co. Tools Scout _____
 Spudded _____ Completed _____ Initial Production _____
 Bond Status _____

ACID RECORD

Casing and Cementing Record

Size	Feet	Inches	Sax Cement
<u>10 3/4</u>	<u>30</u>		<u>20</u>
<u>7</u>	<u>3000</u>		<u>300</u>
<u>5 1/2</u>	<u>3665</u>		<u>Swine</u>

Gals.

Prod.	Date
Prod.	Date
Top Pay	Total Depth

SHOOTING RECORD

No. of Quarts	<u>50</u>	Shot at	<u>3605</u>	Feet	<u>31</u>
No. of Quarts		Shot at		Feet	

Date		Date	
<u>1-10</u>	<u>T.D. 725 H</u>	<u>FEB 28 1939</u>	<u>φ 3130 L-H</u>
	<u>S.D. Orders</u>		
<u>1-17</u>	<u>φ 2433 H-L</u>	<u>MAR 7 - 1939</u>	<u>φ 3235 L</u>
<u>JAN 24 1939</u>	<u>φ 2795 H-L</u>		<u>5 BWP H 3185 S</u>
	<u>3/4 W B R S</u>		<u>H FSW 3200 S</u>
	<u>Ran Schlumberger</u>	<u>MAR 14 1939</u>	<u>Drill 3476 2ND</u>
	<u>2723.</u>	<u>MAR 21 1939</u>	<u>φ 3592 L</u>
<u>JAN 31 1939</u>	<u>φ 2998 L</u>		<u>3/4 3492 S+L</u>
	<u>Lost Circ 2907</u>		<u>1/2 BWP H</u>
<u>FEB 7 - 1939</u>	<u>T.D. 3001 L</u>	<u>MAR 28 1939</u>	<u>T.D. 3640 L</u>
	<u>WOC</u>		<u>φ by Tools</u>
	<u>WOST</u>		<u>5/8 3606 - 31 Rod S</u>
<u>FEB 14 1939</u>	<u>T.D. 3002 L</u>		<u>55/0 - Lost Tools</u>
	<u>R.V.S.T.</u>		<u>wh/ C.D.</u>
<u>FEB 21 1939</u>	<u>T.D. 3002 L</u>		
	<u>prop to plug</u>		

LOG

Depth	Formation	Depth	Formation	Depth	Formation
APR 4 - 1939	φ 36 55 L				
	Can Ritta 36 30				
APR 11 1939	T.D. 36 55 L				
	Fishing Ritta				
APR 18 1939	T.D. 36 55 L				
	fishing Ritta				
APR 25 1939	✓				
MAY 3 - 1939	φ 36 75 L				
	6 BWP #				
S-10	φ 37 70 L				
5/14/39	φ 38 55 L				
5-24-39	φ 40 00 Sdy L				
	S/W 38 70 - 40 S				
S-31	T.D. 41 15 L				