



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Location **Artesia**

Well No. **N.M.06370**

Language **English-Federal**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Temporary abandonment

INDICATE ABOVE BY CHECK MARK AND DATE REPORT, NOTICE OR OTHER DATA

Operations: **English-Federal No. 2**

7-25-60, 19__

Well No. **2** is located **660** ft. from **N** line and **1980** ft. from **W** line of sec. **20**

NE 1/4 of NE 1/4 of Sec. 20 (Twp.) **19 S 31 E** **N.M.P.M.** (Meridian)

Un-surveyed (Field)

Edley (County or Subdivision)

New Mexico (State or Territory)

The elevation of the derrick floor above sea level is **Appx. 3428** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 7-21-60, Welox ram Baker cast iron bridge plug set at 2100', dumped 1 sack cement on top. Plate bolted on top. Well temporarily abandoned. Rods and tubing was pulled prior to plugging.

ILLEGIBLE

APD

I understand that this plan of work, once it is approved, is subject to the Geological Survey before operations may be started.

Company: **Sun Oil Company**

Address: **P. O. Box 2792**

Odessa, Texas