



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4  
Approval expires 12-31-60.

Land Office Santa Fe

Lease No. NM 016011

Unit \_\_\_\_\_

RECEIVED  
FEB 17 1961  
D.C. in  
ARTESIA OFFICE

Inspected  
1-30-61  
by  
Brown

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

Plugging

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 2, 1959

Well No. 1 is located 990 ft. from N line and 660 ft. from W line of sec. 23

24 1/4 24 1/4 Sec. 23  
(1/4 Sec. and Sec. No.)

19  
(Twp.)

31E  
(Range)

NM  
(Meridian)

Art. Lusk  
(Field)

Art.  
(County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is 3546 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well drilled to T.D. of 2468'. Mudded same back to 2250'. Ran 20 sack plug cementing back to approximately 2100'. Mudded back to approximately 875'. Lined off 8 5/8" pipe which was set at 805'. Ran 20 sack cement plug, coming back to approximately 715'. Filled to surface and set marker with 5 sack cement plug.  
Witnessed by Kanauff

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company R. D. Collier

Address Box 921

Artesia, New Mexico

By Regal Guzman

Title Clerk