

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office

Lease No. 0305183

Unit

APPROVED
MAR 14 1963
A. R. BROWN
DISTRICT ENGINEER

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

MARCH 14

1963

J. H. FELCH SINGLAIR

Well No. 1 is located 900 ft. from ^N line and 630 ft. from ^E line of sec. 3
NE 1/4 Sec. 3 190 375 N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
UNDESIGNATED 9001 NEW MEXICO
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

ON 12/17/62 WE RAN 202 FEET OF 10" CASING AND MUDDERED SAME. WATER WAS COMPLETELY SHUT OFF. ON 1/25/63 WE PULLED ALL OF THE 10" CASING AND PLUGGED HOLE.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company J. H. FELCH
P. O. BOX 496
Address ARTESIA, NEW MEXICO

By *[Signature]*
Title OWNER