

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Form Approved.

Land Office **LAS CRUCES**
Lease No. **029387 (B)**
Unit **RECEIVED**

AUG 29 1963

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

SANDRAO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

AUGUST 10, 1963

V. S. WELCH SHUGART

Well No. **9-D** is located **330** ft. from **N** line and **330** ft. from **W** line of sec. **20**

SW SW SEC. 20
(1/4 Sec. and Sec. No.)

183
(Twp.)

31E
(Range)

N.H.P.M.
(Meridian)

R. SHUGART
(Field)

EDDY
(County or Subdivision)

NEW MEXICO
(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

ON AUGUST 8, 1963 SPARKED THROUGH PERFORATIONS IN THE 5-1/2" CASING FROM 3758-50" WITH 1200 BBL. OF LEASE OIL AND 60,000# OF SAND.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **V. S. WELCH**

DRAWER #

Address **ARTESIA, NEW MEXICO**

By

Title

AGENT