Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR

N.M. Oil Cons. Division 811 S. 1st Street

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

	BUREAU OF LAND MAN		Artesia,	NM 8821	0-2834	erial No.	683	
BUREAU OF LAND MANAGEMENT Artesia, NM 8821 SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side					7. If Unit or CA/Agreement, Name and/or No.			
SUBMIT IN TH		- 45° 5						
1. Type of Well								
Oil Well Gas Well					8. Well Name and No.			
2. Name of Operator					Monsanto Foster SWD #1			
Yates Petroleum (Page	9,70			9. API Well No.			
3a. Address	1 1111	3b. Phone No. (include Grea code)			30-015-10340 10. Field and Pool, or Exploratory Area			
105 S. 4th St		505-748-147			SWD - Devonian			
4. Location of Well (Footage, Sec	on)	G DOED (TO A NUMBE)			11. County or Parish, State			
660' FNL & 660' F	WL of Section 5-T2	20S-R25E (LOT 4, NV	(MM)	11. County	01 1 41131	, 5	
		िया का क्षा है हैं है			Eddy Co., NM			
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, F								
12. CHECK AF	PROPRIATE BOX(ES) T	OINDICATI			EFORT, O	KOIII	<u> </u>	
TYPE OF SUBMISSION			TYPE C					
	☐ Acidize	Deepen		Production (Start	/Resume)	□ w:	ater Shut-Off	
Notice of Intent	Alter Casing	Fracture 7	reat	Reclamation		□ w	ell Integrity	
	Casing Repair	New Cons		Recomplete		X Ot	her Remedial Work	
Subsequent Report		Plug and		Temporarily Ab	andon			
Final Abandonment Notice	Change Plans	Plug Back		Water Disposal				
13. Describe Proposed or Complete	Convert to Injection			-			imate duration thereof	
Attach the Bond under which following completion of the intesting has been completed. Feetermined that the site is ready Propose to perform 1. Perform Casing BLM-Carlsbad (505 on chart. If tes	n Casing Integrity g Integrity Test887-6544) in suff t is not good, pro	on results in a mile be filed only aff Test and If test : icient time ceed as for and 3-1	perform js good, ne to wit ollows:	on or recompletion onts, including reclarations, including reclarations of the control of the co	in a new inte amation, have ork as f -Artesia g Integr tubing.	rval, a Fo been con Eollow a (505 rity T	rm 3160-4 shall be filed once inpleted, and the operator has s: -748-1283) and sest and recording	
3. TIH with 2-7/	8" workstring, pac nulus to 900 psi a ssure, may indicat	ker and Ri nd wait 10	BP. Set O minutes	RBP at 101 to see if	70' and pressul	re bie	eas oil. II	
4. Pressure up o 10 minutes. When POOH with tubing WOC 24 hours. Pr 5. Drill out cem squeezed interval	n tubing to 1200 p leak has been iso and tool. TIH wit essure test — if n ent retainer and C	lated, es h CIBP or ot good.	tablish a RBP and resqueeze with tub	end injecti cement ret until a g ing, packe	on rate ainer. ood squo r & RBP	and a Squee eeze : and p	eze as necessary. Es obtained.	
14. I hereby certify that the forego Name (Printed/Typed)	CONTINUED ON NEXT PAGE:							
Rusty Klein	Title Operations Technician							
Signature List	Klen		Date					
- yes	THIS SPACE	FOR FEDER	AL OR STAT	re office USI	E			
Approved by (ORIG.	SGD.) DAVID R. GLAS			EUM ENGIN		Date	JUL 1 8 2000	
Conditions of approval, if any, ar certify that the applicant holds le which would entitle the applicant t	e attached. Approval of this no	tice does not wa	rrant or					

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



YATES PETROLEUM CORPORATION Monsanto Foster SWD #1 Section 5-T20S-R25E Eddy County, New Mexico

SUNDRY NOTICE CONTINUED:

- 6. If interval holds pressure, unset packer and leave hanging at 10000' unset. Pressure casing to 1100 psi for 10 minutes. If pressure holds, continue the pressure test for 35 more minutes. If casing holds pressure for 45 minutes, continue on. If casing does not hold pressure, use packer and RBP to locate leak(s) in casing. Squeeze as necessary. NOTE: Following intervals have been squeezed in the past: 6450-6500', 8159-8222' and 8974-9282'
- 7. Hydrotest packer and 3-1/2" plastic coated tubing in the hole. Set packer at 10180'±.
- 8. Nipple down BOP and nipple up wellhead. Load annulus with 121 bbls of packer fluid containing oxygen scavenger and biocide. Perform Mechanical Integrity Test and record on chart. NOTIFY OCD-ARTESIA (505-748-1283) AND BLM-CARLSBAD (505-887-6544) IN SUFFICIENT TIME TO WITNESS MECHANICAL INTEGRITY TEST

Rusty Klein

Operations Technician

June 30, 2000