

NUMBER OF COPIES RECEIVED 4	
DISTRIBUTION	
SANTA FE	
FILE	7-
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRODUCTION OFFICE	
OPERATOR	2

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

1650/W 2310/N

Name of Company Kersey & Company		Address P. O. Box 316, Artesia, New Mexico	
Lease Bass	Well No. 3	Unit Letter F	Section 12
Township 19S		Range 28E	
Date Work Performed	Pool East Millman Queen Grayburg	County Eddy	

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☐ Other (Explain):
- ☒ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Placed 20 sack cement plug @ 1900'

Mudded back to 500'

Placed 20 sack cement plug below surface casing 420' - Mudded to surface - set marker in cement.

Recovered 1350' of 5" casing and 250' of 8 5/8" casing.

RECEIVED

JUL 15 1965

ARTESIA, N.M.

Witnessed by	Position	Company
--------------	----------	---------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P BTD	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge.	
Approved by W. A. Gressett	Name Harold Kersey		
Title Oil and Gas Inspector	Position Owner		
Date AUG 24 1965	Company Kersey & Company		