

NO. OF COPIES RECEIVED	6
DISTRIBUTION	
SANTA FE	1
FILE	1-
U.S.G.S.	
LAND OFFICE	
OPERATOR	4

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil / Gas Lease No.
<b>E - 100 11</b>

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Sunray Oil Company</b>	8. Farm or Lease Name <b>N.M. State "Y"</b>
3. Address of Operator <b>P.O. Box 128, Hobbs, New Mexico</b>	9. Well No. <b>4</b>
4. Location of Well UNIT <b>M</b> <b>990</b> FEET FROM THE <b>South</b> LINE AND <b>990</b> FEET FROM <b>West</b> LINE, SECTION <b>32</b> TOWNSHIP <b>18</b> RANGE <b>31</b> NMPM.	10. Field and Pool, or Wildcat <b>Shugart (I. SR. Q.G.)</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3557.5 GR</b>	12. County <b>Eddy</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

### SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
WELL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Drilled to TD 3602. Ran 111 jts 4 1/2", 11.6 & 9.5#, J-55 Csg. to C.P. 3576. Cmt'd w/380 ax Incore Pos. WOC 24 hrs. Test csg to 1000# 30 min. OK.
2. Perf 2 holes /ft. @ 3483, 3475, 3465, 3261, 3251, 3024, 3021, 2598, 2596.
3. Treat perms w/2000 gal Spearhead acid & frac w/30,000 gal ref. oil & 6,000# sand.
4. Swab test produced no oil or gas. Put well on T.A. status until we determine final disposition.

RECEIVED

JUN 25 1965

O. C. C.  
ARTESIA, OFFICE

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B.F. Brawley TITLE District Engineer DATE 5-6-65

APPROVED BY W.A. Gressett TITLE Oil and Gas Inspector DATE JUN 25 1965

CONDITIONS OF APPROVAL, IF ANY: