

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate*
(Other instruct. on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-05470-C

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME RECEIVED

8. FARM OR LEASE NAME Simon-A DEC 31 1980

9. WELL NO. 2 O. C. D.

10. FIELD AND POOL, OR AREA Lusk, Strawn

11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA

14,195,31E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Phillips Petroleum Company

3. ADDRESS OF OPERATOR

Room 401, 4001 Penbrook St., Odessa, Texas 79762

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

(Unit P) 660' FS & AE lines

14. PERMIT NO.

NA

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3558' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Installed artificial lift equip. X

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12-11-80 MI Well Unit. ND BCP's, pulled rods and tubing. Installed 338--3/4" rods, 112--7/8" rods, and 2" x 1-1/4" x 20' pump. Set tubing at 11311' and pump at 11312'. Mo Well Units. Pumped 24 hours--6B0, -0- water, 30,000 GOR from 4-1/2" casing perfs 11,332-11,364'.

322-548
11356-64

Series 900 BCP 3000# WP double w/one set blind rams, one set pipe rams.

18. I hereby certify that the foregoing is true and correct

SIGNED

W. J. Mueller TITLE Sr. Engineering Specialist

DATE Dec. 15, 1980

(This space for Federal Use)

APPROVED BY PETER W. CHESTER

TITLE

DATE

CONDITIONS OF APPROVAL IF ANY

DEC 30 1980

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side