

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐  
well well

2. NAME OF OPERATOR  
Dorchester Gas Corporation

3. ADDRESS OF OPERATOR  
P. O. Box 96, Hobbs, New Mexico 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1980' FSL & FWL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) ☐

SUBSEQUENT REPORT OF:

☐  
☒  
☐  
☐  
☐  
☐  
☐  
☐  
☐

RECEIVED  
DEC 30 1981

U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

5. LEASE  
New Mexico 0554775  
6. IF INDIAN, ALLOTTEE OR TRIBE RECEIVED  
7. UNIT AGREEMENT NAME  
DEC 31 1981  
8. FARM OR LEASE NAME  
Dozier Federal Com. O. C. D.  
9. WELL NO.  
1  
ARTESIA, OFFICE  
10. FIELD OR WILDCAT NAME  
Lusk Strawn  
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 14, T. 19 S., R. 31 E.  
12. COUNTY OR PARISH  
Eddy  
13. STATE  
New Mexico  
14. API NO.  
30-015-10804  
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3535 GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

12/22/81 Pmpd 80 bbls. heated lease oil down csg annulus, pmpd up tbg. Dumped 2100 gal. (50 bbls.) of 15% FE acid w/1.5 gal HAI-50/1000 gal, 5 gal. 14-N/1000 gal. and 1 bbl. parasperse down csg annulus and flushed to perms w/140 bbl 2% KCL water. Well went on vacuum. SI overnight and returned well to pmpg status. (80 BLO and 191 BLW to recover.)

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Steve Galt TITLE District Engineer DATE 12/28/81

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

ACCEPTED FOR RECORD

DEC 30 1981  
O.C.D.  
U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXIC