

NO. OF COPIES RECEIVED	
() SUBMITTED TO	
SANTA CRUZ	
P.O.	
MEXICO	
LARGE PRINT	
COPY DATE	

RECEIVED BY

JAN -2 1987

Q. C. D.

110 2088

NEW MEXICO 87501

ARTESIA, OFFICE

5a. Indicate Type of Lease

State X

From []

5. State Oil & Gas Lease No.

OG-605

7. Unit Agreement Name

8. Firm or Lease Name	
-----------------------	--

Lowe B State

C. Wall No.

#3

Field and Pool, or Wildcat

Artesia Qn Gr SA

Fast

195

1205

only

Eāday

Report or Other Data

SUBSEQUENT REPORT OF:

ALTERING CARING

PLUG AND ABANDONMENT

10-1-68. Ran 4 1/2" BP and cemented on top of plug.
10-2-68. Perforated @ 1650' and 650'. Ran 10 jts tail pipe 4 1/2" tension packer and 41 jts. of 2" tubing. Set packer and tested to see if it would hold fluid. Did not take. Spotted 25 SXS plug @ 1600'. Pulled tube and packer out of hole. Perforated @ 650'. Pumped 45 Sxs. while running and circulating. Let run 2 hrs and checked cement @ 450'. Set 10 SXS tension plug.

Post ID-2
1-23-87
P+H

Secretary

DATE 12-5-86

W I C H I T

٢٠٤

TITLE OIL AND GAS INSPECTOR

DATE JAN 12 1988

APPROVED BY Y. H. H. H. H. H.