

MAY 1963)

Copy to SF

DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Operator

Roger C. Hanks

Address

2000 Wilco Building, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

660' FNL &amp; 660' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3565' GR

5. LEASE DESIGNATION AND SERIAL NO

NM 0559175

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

DAGGER DRAW

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

30-19S-25E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

Spud &amp; Surface Casing

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

5-7-70 Spudded 17½" hole at 1:00 a.m.

5-11-70 Depth 930'. Ran 930' of 13 3/8" 48# casing. Cemented with  
800 sx. (700 sx regular & 100 sx 2% CC)5-12-70 Ran temperature survey to possible tops of cement, first  
being at 700', the second at 314'. Ran second temperature  
survey at request of U.S.G.S. No result. Staged cement with  
50 sx neat 3% CC. Last stage of cement visible from surface  
but dropped in 5 min. Gravel packed to run additional stages  
to assure cement around top of surface casing. Recemented  
outside 13 3/8" with 100 sx.  
WOC.

5-13-70 Commenced drilling at 9:30 p.m.

RECEIVED

JUN 4 1970

18. I hereby certify that the foregoing is true and correct

O. C. C.

SIGNED

TITLE Operator

DATE 5-26-70

(This space for Federal or State use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

ACCEPTED FOR RECORD PURPOSES

JUN - 3 1970  
Date

ACTING District Engineer

\*See Instructions on Reverse Side