rm 3160-5 me 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Drawer /D Artesia, Ni

NM OIL TONS COMVISSION

FORM APPROVED Budget Bureau No. 1004-0135

Expires: March 31, 1993

5. Lease Designation and Serial No.

SUNDRY NOTICES AND REPORTS ON WELL 20 Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals		NM-82845
		6. If Indian, Allottee or Tribe Name
CURNIT IN TRIBUTOATE		7. If Unit or CA, Agreement Designation
SUBMIT IN TRIPLICATE		_
Type of Well Oil Gas		8. Well Name and No.
Oil Well WX Well Other Name of Operator		Polo AOP Federal Com #2
YATES PETROLEUM CORPORATION	(505) 748-1471)	9. API Well No.
Address and Telephone No.	(303) 740 1471)	30-015-20334
105 South 4th St., Artesia, N	JM 88210	10. Field and Pool, or Exploratory Area
Location of Well (Footage, Sec., T., R., M., or Survey Description)		Boyd Morrow
	on 10-T19S-R25E (Unit J, NWSE)	11. County or Parish, State
		Eddy Co., NM
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPO	
TYPE OF SUBMISSION	TYPE OF ACTION	 ,
Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
X Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	XX Other Re-entry	Dispose Water {Note: Report results of multiple completion on Well
		Completion or Recompletion Report and Log form.)
	Il pertinent details, and give pertinent dates, including estimated date of startin cal depths for all markers and zones pertinent to this work.)*	g any proposed work. If well is directionally drilled,
10-20-94 - Drilled. TOOH wit	h $3-3/4$ " bit. TIH $w/3-13/16$ " flat bot	tom cutrite shoe with 13'
extension, Bowen jars, 8 3-1/8	8" drill collars and tubing. Milled 5	hours. TOOH with mill.
Change shoe and TIH with 3-7/8		
10-21-94 - Milled for 5 hours	. Torqued hard. TOOH. TIH w/3-3/4"	magnet. TOOH. TIH with
drill collers and tubing To	down at 9104'. TOOH. TIH with 2-3/8	" notched collar, jars,
drill collars and tubing. Tag at 9104'. Displace mud with 9.2# cut brine. Rotate and torque 20 minutes, fell through. Wash sand out to 9165'. Solid bottom. TOOH & lay down 3-1/8"		
drill collars. TIH with 3-3/4	4" bit and scraper to 9000'. TOOH.	100H & 1ay down 3-1/8"
10-22-94 - TOOH with bit and	scraper. TIH with 4-1/2" 10K Uni VI p	acker with 1 81" VI on/off
tool, 94 joints of 2-3/8" N-80	0 tubing & 180 joints of 2-3/8" J-55 t	uhing. Nippled down ROP
Nippled up tree. Set packer a	at 8915'. Tested annulus to 1000 psi.	Swabbing perforations
9024-9151' (Morrow).	•	
10-22-94 - Swabbing.		
10-23-94 - Swabbing.		
10-24-94 - Loaded tubing. Re	leased packer. Nippled down tree. Ni	ppled up BOP. TOOH. TIH
of $2-3/8$ " N=80 tubing Piage	Lok Uni V packer, 8 joints of 2-3/8"	J-55 tubing & 94 joints
Tested to 1000 psi Set packs	d up wireline. Ran GR/CCL to position er at 8915'. Nippled down BOP and nip	tools. Set RBP at 90/5'.
annulus/to 1000 psi Swabbing	Morrow perforations 9024-9051'.	pled up tree. Tested
4. I hereby certify that the foregoing is true and correct		
Signed Kustey Ilu	Title Production Clerk	Date Oct. 27, 1994
(This space for Federal of State office use)		
Approved by	Title	Date
Conditions of approval, if any:		
		₩