

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SURMIT IN TRIPPLICATE*
(Other Instructions on re-verse side)

Form approved.
Budget Bureau No. 42-11424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR GULF OIL CORPORATION		8. FARM OR LEASE NAME Littlefield "AB" Federal	
3. ADDRESS OF OPERATOR P. O. Box 670, Hobbs, New Mexico 88240		9. WELL NO. 13	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL & 660' FEL		10. FIELD AND POOL, OR WILDCAT Shugart (Y - SR- Q - G)	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 22, T-18S, R-31E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3651' GL		12. COUNTY OR PARISH Eddy	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <u>Inspected & Filled Cellar</u>	<input checked="" type="checkbox"/>

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Piped valves off each casing string above ground level. Inspected by Byrd Jones with U. S. Geological Survey, 2-12-79. Filled cellar, 2-13-79.

RECEIVED

FEB 15 1979

U.S. GEOLOGICAL SURVEY
ALBUQUERQUE, N.M.

18. I hereby certify that the foregoing is true and correct

SIGNED N. B. Sikes Jr. TITLE Area Engineer DATE 02-13-79

(This space for Federal or State office use)

APPROVED BY Lee S. Lara TITLE ACTING DISTRICT ENGINEER DATE FEB 15 1979

CONDITIONS OF APPROVAL, IF ANY: