Form 3160-5 (June 1990)

## **UNITED STATES** MENT OF THE INTERIOR DEI **BUREAU OF LAND MANAGEMENT**

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

6. If Indian, Allottee or Tribe Name

NM (	0291	28
------	------	----

**SUNDRY NOTICES AND REPORTS ON WELLS** 

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.	
Use "APPLICATION FOR PERMIT " for such proposals	

Do not use this form for proposals to drill or to Use "APPLICATION FOR PER		rvoir.		
SUBMIT IN TRIPLICATE			7. If Unit or CA, Agreement Designation	
Type of Well Oil Well Swell Other  Name of Operator Hallwood Petroleum, Inc.  Address and Telephone No. P. O. Box 378111, Denver (303) 850-6257	er, CO 80237	(3) (3) (5)	8. Well Name and No.  Catclaw Draw Unit #9  9. API Well No. 30-015-20860  10. Field and Pool, or Exploratory Area	
Location of Well (Footage, Sec., T., R., M., or Survey Description) 650' FNL & 1980' FWL - Section 35 - T21S-R25E			Catclaw Draw Morrow  11. County or Prish, State Eddy County, NM	
2. CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOT	ICE, REPO	RT, OR OTHER DATA	
TYPE OF SUBMISSION		TYPE OF	ACTION	
Notice of Intent Subsequent Report Final Abandonment Notice	☐ Abandonment ☐ Recompletion ☐ Plugging Back ☐ Casing Repair ☐ Altering Casing ☐ Other		☐ Change of Plans ☐ New Construction ☐ Non-Routine Fracturing ☐ Water Shut-Off ☐ Copnversion to Injection ☐ Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
<ol> <li>Describe Proposed or Completed Operations (Clearly state all pertinent de locations and measured and true vertical depths for all markers and zones</li> </ol>	tails, and give pertinent dates, including estimated date pertinent to this work.) *	of starting any p	proposed work. If well is directionally drilled, give subsurface	

Hallwood treated the Morrow 'C' with 4,000 gals of 10% NeFe acid w/ CO2 and 100 ball sealers. This did not restore gas production, we plan to monitor this well for 30-60 days and evaluate to test the Strawn zone uphole or P&A the well.

