

COPIES RECEIVED	3
PRELIMINATION	
FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

JUL 1 1974

O.C.C.

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - "A" FORM C-1011 FOR SUCH PROPOSALS.

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Coquina Oil Corporation ✓		5. State Oil & Gas Lease No. K-4094
3. Address of Operator 200 Bldg. of Southwest, Midland, Texas 79701		7. Unit Agreement Name
4. Location of Well UNIT LETTER J 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 19 TOWNSHIP 19S RANGE 29E N.M.P.M.		8. Farm or Lease Name Flag State
15. Elevation (Show whether DF, RT, GR, etc.) G. L. 3342		9. Well No. 1
		10. Field and Pool, or Wildcat Wildcat
		12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Progress

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work; SEE RULE 1103.)

Drilled a 7 7/8" hole to a total depth of 11,650'. Ran 50 jts. of 5" 18# N-80 Buttress casing and 271 jts. of 5 1/2" 17# N-80 8rd casing and set at 11,574'. Cemented with 600 sacks of Class H with 1% CRF-2 and 5# kcl per sack. Plug down at 3:30 A.M, 6-28-74. Float did not hold. Ressed up to 2000 psi for 15 minutes. Rechecked float - did not hold. Pressured up to 2000 psi for 4 hours. Rechecked float - held OK. Preparing to complete well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D.C. Radtke (D.C. Radtke) TITLE Engineer DATE 6-28-74

APPROVED BY W. R. Gressett TITLE OIL AND GAS INSPECTOR DATE JUL 2 1974