NO. OF TOPIES RECEIVED		Form C-103
DISTRIBUTION .	•	Supersedes Old
DISTRIBUTION	NEW MEXICO OIL CONSER FA FOR COMMISTOP	C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-55
		Fa indiana Turnini
U.S.G.S.	JUN 3 1 974	State X Fee
LAND OFFICE		5. State Oil & Gas Lease No.
OPERATOR	O. C. C.	K-4093
CHAIDDA	APPLA REFER	mmmilink
OUNUAL I (DO NOT USE THIS FORM FOR PACPOS USE "APPLICATION	NOTICES AND REPORTS ON WELLS ALS TO DAILL OR TO DEEPEN OF PLUG BACK TO A DIFFERENT RESERVOIR. FOR PERMIT - " (FCAM C-101) FOR SUCH PROPOSALS.)	
1.	TO THE TOTAL OF TH	7. Unit Agreement Name
OIL GAS WELL X	OTHER-	
2. Name of Operator		8. Farm or Lease Name
Hondo Drilling Company /		Union TX State Com.
Hondo Drilling Company 3. Address of Operator		9. Well No.
P.O. Box 2516, Midland, Texas 79701		No. 1
		10. Field and Pool, or Wildon
UNIT LETTER N 6601 FEET FROM THE South LINE AND 19801 FEET FROM		Wildcat Wildcat
	4	
THE West Line, SECTION 17 TOWNSHIP 19 South HANGE 39 East NMPP		MPM. (
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
ŽIIII:IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	3379 RT	Eddy ///////
Check App	propriate Box To Indicate Nature of Notice, Report or	Other Data
NOTICE OF INTE	ENTION TO: SUBSEQU	ENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORAFILY ABANDON	COMMENCE DRILLING OPNS.	THEMHOCHABA DHA DULA
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JQB [X]	F
CTHER	OTHER	
OTHER		
17. Describe Proposed or Completed Operat	tions (Clearly state all pertinent details, and give pertinent dates, inclu	iding estimated date of starting any propos
worty see Roce 1103.		
As of $5/29/7L$ cable tool	L operations were suspended at a depth of l	001, and rotary
tools were moved to this location with rigging up operations commenced.		
4.4.54.4 4.4 5.4		
On 6/1/74 @ 1:00 P.M. dr	rilling operations were resumed with rotary	tools.
	,	
On 6/2/74, 375' of 17-1/	/2" hole had been drilled @ 2:15 A.M. 375'	of 13-3/8" 48# casing
	L'GL. 275 sax of Halliburton light cement	
	c of neat cement with 2% Cal. chloride was	
	Cement did not circulate. It was necessary	
gravel and 8 yards of re	eady mix cement to bring cement operations	back to surface.
101 7/1	70.7 / 1111 / 0201	1 2000 // DG: 0 00
	up ran 12-1/4" bit to 310', tested casing	
minutes without pressure	e drop, and commenced drilling plug after a	pprox. 20 nrs. WUC.
0- £/2/71 +bis 20077 -ma	dmillion at 010 fact of a co	
OH 9/3/14 CHIS WELL WAS	drilling at 810 feet. @ 8:00 A.M.	
	<u> </u>	
18. I hereby certify that the information abo	we is true and complete to the best of my knowledge and belief.	
70/	W	/ /2 /51
SIGNED	Vice president	DATE 6/3/74
2.112 4.	OIL AND GAS INSPECTOR	JUN 4 1974
APPROVED BY MCCI	TITLE VIL AND ONG INGIEGION	DATE

CONDITIONS OF APPROVAL, IF ANY: