

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN T. CATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER
2. NAME OF OPERATOR **Barbara Fasken**
3. ADDRESS OF OPERATOR **303 W. Wall, Suite 1900, Midland, Texas 79701-5116**
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

5. LEASE DESIGNATION AND SERIAL NO.
NM-19418
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Feil Federal
9. WELL NO.
1
10. FIELD AND POOL, OR WILDCAT
Cemetery (Morrow)
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 28, T-20-S, R-25-E
12. COUNTY OR PARISH
Eddy
13. STATE
New Mexico

Unit D, 660' FNL & 660' FWL, Sec. 28, T-20-S, R-25-E

14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3526 G.L.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANE ☐
(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☒ ABANDONMENT* ☐
(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

- 12-20-90 thru 01-02-91
1. Perforated additional morrow pay as follows: 9527-32', 9514-24', 9494-9504', 9470-74', 9458-61', 9436-38', 9431-33', 9341-45', 9329-32', 9311-15', 9292-94', 9270-75', 9263-66', 9155-61' and 9133-43', with 2 JSPF.
 2. Swabbed well and flare tested to pit.
 3. Put on line to NGPL.

RECEIVED
JAN 24 10 05 AM '91
CARLOS J. GARCIA
AREA ENGINEER

18. I hereby certify that the foregoing is true and correct

SIGNED C. Lynn Smith

TITLE Engineering Assistant

DATE 01-21-91

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

*See Instructions on Reverse Side