

Copy to S.F.

10CC COPY

Form 9-351
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR <u>Visa Exploration Corporation</u>		8. FARM OR LEASE NAME <u>Federal 26</u>	
3. ADDRESS OF OPERATOR <u>1610 North J, Midland, Texas 79701</u>		9. WELL NO. <u>4</u>	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <u>990' FNL & 1980' FEL</u>		10. FIELD AND POOL, OR WILDCAT <u>Shugart</u>	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>3654' GR</u>	
		12. COUNTY OR PARISH <u>Eddy</u>	18. STATE <u>N. Mex.</u>

RECEIVED

FEB 10 1978

D. D. C.
ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <u>Run & cement surface casing</u> <input checked="" type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded @ 12:30 p.m. on 1/25/78.

Drilled 11" hole to 835'. Circulated 30 minutes. Ran 20 jts. (830') of 8 5/8" 28# csg. and set 814' @ 826'. Cemented w/175 sx Halliburton Lite w/5# Gilsonite & 1/4# Flocele/sx plus 200 sx Class "C" w/2% CaCl. Plug down @ 9:15 p.m. on 1/26/78. Circulated out approximately 66 sx cement. Float held O.K. 18 hours after plug was down, tested csg. to 650 psi for 30 minutes - 30# drop in pressure.

RECEIVED
FEB 6 1978
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Neal A Taylor TITLE Agent DATE 2/2/78

(This space for Federal or State office use)

APPROVED BY Joe D. Lara TITLE ACTING DISTRICT ENGINEER DATE FEB 9 - 1978

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side