

NM OIL CONS. COMMISSION
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT TO THE STATE
(OTHER INSTRUCTIONS ON REVERSE SIDE)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
NM-30629

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1981

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Eastern Shore "QW" Federal

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

Wildcat Morrow

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Unit J, Sec. 8-T19S-R27E

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR
Yates Petroleum Corporation

3. ADDRESS OF OPERATOR
207 South 4th St., Artesia, NM 882 0

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface 1623' FSL & 1693' FEL

14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
1334' GR

12. COUNTY OR PARISH
Eddy
13. STATE
NM

16. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLET

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Production Casing

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Lost circulation at 8988'. Set cement plugs at 7832 & 7000'. Drilled out cement plugs with full returns. TD 10158'. Ran 251 jts of 5-1/2" 17# K-55 & N-80 casing set at 10158' as follows: Ran 47 jts 5-1/2" 17# N-80 LT&C, 177 jts 5-1/2" 17# K-55 LT&C & 27 jts 5-1/2" 17# N-80 LT&C. Diff-fill shoe set at 10158' & diff-float collar at 10118'. Ran 6 bbls flush ahead w/25 sacks Excellon-gel w/50# KCL. Cemented w/150 sacks 50/50 Poz, 3#/sack KCL, .6% CF-9 & .3% TF-4. Tailed in w/325 sacks Class "H" Shallowseal, 3#/sack KCL, .6% CF-9 & .3% TF-4. PD 12:45 Am 8-26-81. Bumped plug to 500 psi, released pressure & float held okay. WOC. 700 6650

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Engineering Secretary

DATE 8-31-81

(This space for Federal or State official use)
ROGER A. CHAPMAN

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL IF ANY:
SEP 8 1981

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side