

NM OIL CONS. COMMISSION  
Director ED  
Artesia, NM 80510

Form 9-331  
Dec. 1973

Form Approved.  
Budget Bureau No. 42-R1424

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

5. LEASE  
NM-14747

6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
RECEIVED

7. UNIT AGREEMENT NAME  
JAN 6 1982

8. FARM OR LEASE NAME  
Panos Fed. Com. O. C. D. ARTESIA, OFFICE

9. WELL NO.  
1

10. FIELD OR WILDCAT NAME  
Undesignated Antelope Sink (Morrow)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 1, T19S, R23E

12. COUNTY OR PARISH | 13. STATE  
Eddy | New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3811' GR

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well  gas well  other

2. NAME OF OPERATOR  
Exxon Corporation /

3. ADDRESS OF OPERATOR  
P. O. Box 1600, Midland, TX 79702

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1980' FNL & 660' FEL of Section  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:      SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF      

FRACTURE TREAT      

SHOOT OR ACIDIZE      

REPAIR WELL      

PULL OR ALTER CASING      

MULTIPLE COMPLETE      

CHANGE ZONES      

ABANDON\*      

(other) Spud and set casing

RECEIVED  
JAN -4 1982

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

OIL & GAS  
U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

The above well was spudded on December 26, 1981 and conductor, 20", 94# csg., was set at 40' with Read Mix to surface. Don Clough of Exxon notified Roger Chapman, USGS, of spud date.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct  
SIGNED E. A. [Signature] TITLE Unit Head DATE December 30, 1981

ROGER A. CHAPMAN (This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL JAN 5 1981

U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

See Instructions on Reverse Side