

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ well ☐ well ☒ other

2. NAME OF OPERATOR

Robert N. Enfield

3. ADDRESS OF OPERATOR

P.O. Box 2431, Santa Fe, NM 87501

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
1980' FNL & 990' FEL of Sec. 7
AT SURFACE:
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BCX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐

SUBSEQUENT REPORT OF:

(other) INTERMEDIATE CASING

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The well was spudded at 9:30 AM MDSF, 10/19/87. 13-3/8" casing was set & cemented in place at 320' KB. Drilling then continued with an 12-1/4" bit to 1.498' KB. an 11" bit was used from that point to 2420' KB. Intermediate casing was set & cemented in place at 2420.00' KB as described: All casing is 8-5/8" 24#/ft., ST&C J-55. Bottom to top - float shoe (.85'). 1 jt. of casing (42.00') float collar (1.60') 56 its. casing (2359.55'). Upon reaching set depth, hole was circulated for 60 min. followed by cement as shown below: 10 bbls fresh water, 900 sx Halliburton Lite cement w/1/4# flocele. & 5# Gilsonite/sx. mixed 12.7#/gal., 1.84 cf/sx., 300 sx of Class "H" cement w/2% CaCl mixed 15.6#/gas., 1.18 cf/sx., 147 bbls fresh water. Plug bumped at 2:15 AM 10/24/87; pressure was released & float held. Full returns were noted during cementing. Approximately 140 sx cement circulated to pit. Cementing witnessed by Mr. Danny Cortez of BLM. Tested casing to 1000 PSIG for 30 minutes; OK. Drilled out at 2:15 AM 10/25/87.

* Subsurface Safety Valve: Manu. and Type

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

Robert N. Enfield

(This space for Federal or State office use)

Operator

11/16/87

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

Form Approved.
Bureau No. 42-R1424

NOV 25 1987

5. LEASE

NM-29826

6. IF INDIAN ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Walters Federal

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

Undes McMillan U.Penn(Gas)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 7, T19S, R27E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3271' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330)

533